



FAMU-FSU
College of
Engineering

Team 501

Tribometer in Spacelike Conditions

VDR5 240227



Team Introductions



Branham Channell
Materials Engineer



Cobi Johnson
Systems Engineer



Madison Retherford
Mechatronics Engineer



Javier Ibanez
Structural Engineer



Joshua Wesley
Computer Hardware Engineer




Sponsor and Advisor



Dr. Brandon Krick



Dr. Shayne McConomy





Objective

The objective of this project is to design, develop, and implement a system that enables the simultaneous testing of multiple samples within a vacuum chamber using a tribometer. This system aims to increase testing throughput and enhance overall efficiency while maintaining prior accuracy and control.




What is a Tribometer?

Tribometers measure quantities such as coefficient of friction, friction force, and wear volume on two surfaces in contact by simulating friction in controlled conditions.



AME's Vacuum Chamber

- Vacuum chambers work by removing air and gas from a vessel using a pump.
- The lab's is a bell-style high-vacuum chamber.
- It can reach pressures as low as 1.5×10^{-6} mbar.



Steps to High-Vacuum

Step 1


- Roughing pump pulls initial vacuum on system.
- This "rough vacuum" is around 10^{-1} to 10^{-2} mbar.

Step 2

- Switch to the much stronger cryo-pump.
- Takes vacuum down to 10^{-5} mbar quickly.

Step 3

- Let sit overnight (or at least 12 hours).
- Achieves 10^{-6} mbar range.




Key Goals

Test multiple samples

Control parameters

Operate in specific conditions




Key Goals

Test multiple samples

Control parameters

Operate in specific conditions



Key Goals


Test multiple samples

Control parameters

Operate in specific conditions




Final Concept Selection




6 mini-identical tribometers.

CAD Design: Mach 3 (Front)




CAD Design: Mach 3 (Back)



Motors in tension

Thermal Assembly




Heat to take material from -196C to 200C in 30 minutes:

- Copper substage = 6.28 Watts
- Aluminum counter sample = 1.95 Watts

Maximum heater output is 88 Watts so,

$$Q_{heater} > Q_{copper} + Q_{aluminum}$$




Counter sample


Substage

Minco heater

CAD Design: Load Head



FEA: Stress




Pa (N/m²)



- Force is **evenly distributed** across the leaf spring to **ensure constant and even contact of sample to counter sample**.
- Max stress: ~480 MPa (red)
- Titanium Leaves Yield Strength: ~1100 MPa

FEA: Strain




Equivalent Strain (ESTRN)




Strain is all in the leaf spring and load cells.

Machined Parts: Load Head




Load Cell



- Measures force by converting mechanical strain into electrical signals.
- Output, mV/V , is converted to other units of measurement through calibration.

Amplifier




- Output of the load cell is a small signal, needs to be amplified for better measurements.
- Adjusting the gain decreases signal noise.

Summing Junction



Takes 2 to 4 load cell inputs and combines them into a single output.

Looking at Force on a Load Cell



Future Work

Give large materials to machine shop.

Get large support equipment machined.

Clean all parts to IAW ISO 14644-6.

Assemble parts and run calibration tests.

Future Work

Program the motors.

Interface with MATLAB.

Test heating/cooling system.

Test full system.